
Nabtesco Marine Asia Pacific Pte Ltd

MG-800 Governor Modification Plan for EEXI Compliance


OPTION 1: MECHANICAL EPL

System Configuration



Features

- Unnecessary to modify Governor
- Recording device is not required



OPTION 2: ELECTRIC EPL

System Configuration



Features

- Unnecessary to modify Governor
- Recording device required EPL operation time is short

Staff setting errors may happen during EPL \triangle override and recovery

Available for Controller series












Recommended

OPTION 3: FULL ELECTRIC EPL

3-1 Non Upgrade needed | 3-2 Upgrade needed


System Configuration • BRIDGE **ECR**



The EPL is one of the solution which complies with the MEPC technical guidelines for EEXI "GUIDELINES ON THE SHAFT / ENGINE POWER LIMITATION SYSTEM TO COMPLY WITH THE EEXI REQUIREMENTS AND USE OF A POWER RESERVE"

Features

- Governor Modification is required
- EPL operation time is very short
- No operator errors for limiter switching
- operations from Bridge (optional)







OMM - Onboard Managerment Manual EPL - Engine Power Limitation



www.nabtesco-marine.com.sg